

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940

RECEIVED  
FEB 01 2000  
DIVISION OF  
OIL, GAS AND MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 01/1999 To (mo./yr.) 12/1999
2. DOGM File Number (Mine No): 1 1 M 490032
3. Mine Name: ERins East Quarry, Valley Asphalt, Inc./Western Aggregates
4. Mineral(s) Mined (or permitted to mine): Limestone aggregate
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected): please refer permit  
\_\_\_\_ 1/4, \_\_\_\_ 1/4, \_\_\_\_ 1/4, Section \_\_\_\_, Township \_\_\_\_, Range \_\_\_\_  
\_\_\_\_ 1/4, \_\_\_\_ 1/4, \_\_\_\_ 1/4, Section \_\_\_\_, Township \_\_\_\_, Range \_\_\_\_  
\_\_\_\_ 1/4, \_\_\_\_ 1/4, \_\_\_\_ 1/4, Section \_\_\_\_, Township \_\_\_\_, Range \_\_\_\_
7. Name of Operator or Company: Valley Asphalt, Inc.
8. Permanent Street Address: 1172 South Del Monte Road  
City, State, Zip: Spanish Fork, Utah 84660  
Phone: (801) 798-7486 Fax: (801) 798-8316
9. Company Representative (or designated operator):  
Name: Brent Sumson  
Title: President  
Business Address: 1172 South Del Monte Rd  
City, State, Zip: Spanish Fork, Utah 84660  
Phone: (801) 798-7486 Fax: (801) 798-8316  
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? \_\_\_\_\_
3. If yes - how much ore or mineral was mined? 650,000 approx tons

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

Material was extracted by drilling and blasting. The material was then processed in ~~an~~ an aggregate processing plant. Some of the material was then processed into hot mixed asphalt.

5. How much **additional acreage** was disturbed during the past year? 10 acres (the entire area is bonded)
6. How much acreage was **reclaimed** during the past year? 0 acres
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

N/A

8. What is the **total disturbed acreage of entire project** at years end? approx 25 acres
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Most of the area currently disturbed is used for staging equipment & stockpiles. In a few years after ~~approx~~ more mining area gets exposed, it will be economical to commence reclamation.

**NOTE:** Section III., "Additional Information" applies only to **large mining operations**.

### III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. Signature Requirement

**I hereby certify that the foregoing is true and correct.**

Name (Typed or Print):

ARJUN RAM

Title of Operator:

Vice-President (Western Aggregates, Inc.)

Signature of Operator:

[Signature]

Date:

1/28/2000

jb  
a:\forms\MR-AR

**RECEIVED**

FEB 01 2000

DIVISION OF  
OIL, GAS AND MINING